


STAMP JOB # FROM TRAVELER  
IN AREA UNDER ADJUSTMENT  
SCREWS AND CENTERED



NOTE:  
3 & 4 BANK ASSY'S SAME AS 1 & 2 BANK ASSY.  
THEN ROTATED 45° TO INSTALL ON P/N 1003-149  
4 PLANE CONNECTOR -- #15

ITEM	QTY	PART NUMBER	DESCRIPTION
15	1	1003-149	4-PLANE CONNECTOR
14	12	9001-123	5/16-18 X 1-3/4 FHCS
13	2	1003-177	ALL BANK CONNECTOR
12	4	9805-002	NAMEPLATE
11	1	1300-003	SLIP TORQUE KNOB ASSY N/S
10	24	9001-074	10-32 X 1/2 FHCS
9	8	1003-112	ROLL CAP
8	28	9000-090	1/4-20 X 3/4 SHCS
7	28	9303-171	BEARING "V" GROOVE
6	28	9008-110	.250 ID X .375 OD SHIM WASHER
5	28	1003-130	ROLL PLATE
4	3	9003-407	8-32 X 3/16 SHSS NYLON TIP
3	3	9800-005	.140 ID CERAMIC WIRE GUIDE
2	56	9000-110	1/4-28 X 1-1/4 SHCS ADJUSTMENT SCREW
1	4	1003-111	UNIBODY #3 HOUSING

MACHINE MARK ON BOTTOM  
USED FOR CORRECT POSITION  
OF CONNECTOR

**TRAK**  
ENTERPRISES

BRIDGE, CT.  
www.trakenterprises.com

TOLERANCE UNLESS OTHERWISE STATED:  
 Δ ± .3  
 ∅ ± 0.0003  
 ∅ ± 0.0002  
 ∅ ± 0.0005  
 ∅ ± 0.0005

FRACT +/- 1/16  
 X ± .032  
 XX ± .015  
 XXX ± .005  
 XXXX ± .0005

CAD DWN KPL  
 1003-004  
 PART NAME 1003 4 PLANE EXPLODED ASSY  
 SCALE  
 DATE 4/2/02

REV ECN CHG BY DATE