


STAMP JOB # FROM TRAVELER
IN AREA UNDER ADJUSTMENT
SCREWS AND CENTERED



NOTE:
3 & 4 BANK ASSY'S SAME AS 1 & 2 BANK ASSY.
THEN ROTATED 45° TO INSTALL ON P/N 1003-149
4 PLANE CONNECTOR -- #15

MACHINE MARK ON BOTTOM
USED FOR CORRECT POSITION
OF CONNECTOR

ITEM	QTY	PART NUMBER	DESCRIPTION
15	1	1003-149	4-PLANE CONNECTOR
14	12	9001-123	5/16-18 X 1-3/4 FHCS
13	2	1003-177	ALL BANK CONNECTOR
12	4	9805-002	NAMEPLATE
11	1	1300-003	SLIP TORQUE KNOB ASSY N/S
10	24	9001-074	10-32 X 1/2 FHCS
9	8	1003-112	ROLL CAP
8	28	9000-090	1/4-20 X 3/4 SHCS
7	28	9303-171	BEARING "V" GROOVE
6	28	9008-110	.250 ID X .375 OD SHIM WASHER
5	28	1003-130	ROLL PLATE
4	3	9003-407	8-32 X 3/16 SHSS NYLON TIP
3	3	9800-005	.140 ID CERAMIC WIRE GUIDE
2	56	9000-110	1/4-28 X 1-1/4 SHCS ADJUSTMENT SCREW
1	4	1003-111	UNIBODY #3 HOUSING

REV	ECN	CHK BY	DATE

NOVO
PRECISION

TOLERANCE UNLESS
OTHERWISE STATED
FRACTIONAL DECIMALS
FRACTIONAL DECIMALS
FRACTIONAL DECIMALS
FRACTIONAL DECIMALS
FRACTIONAL DECIMALS

DATE: 4/2/03

QUANTITY / PART NO.
1003-004
PART NAME
1003 4 PLANE
EXPLODED ASSY
CUSTOMER