


3 & 4 BANK ASSY'S SAME AS 1 & 2 BANK ASSY.
THEN ROTATED 45° TO INSTALL ON P/N 1004-205
4 PLANE CONNECTOR -- #14

17	1	1300-140	TORQUE WRENCH (NOT SHOWN)
16	2	9000-150	3/8-16 x 2 SHCS
15	2	9000-152	3/8-16 x 2-1/2 SHCS
14	1	1004-205	#4 FLANGE ADAPTOR CONNECTOR
13	8	9001-149	3/8-16 x 1-3/4 FHCS
12	2	1004-203	#4 UNIVERSAL CONNECTOR
11	4	9003-425	1/4-28 x 3/16 SHCS NYLON TIP (INV.)
10	2	9001-118	1/8-18 x 3/4 FHCS
9	4	1003-202	#4 ROLL CAP
8	28	900M-070	12MM x 1.75 x 30MM METRIC SHCS
7	28	900B-117	WASHERS (INV.)
6	28	9304-166	#4 WIDE "V" BEARING
5	28	900B-118	SHIM WASHER
4	28	1004-201	#4 UNIBODY ROLL PLATE
3	3	9800-012	1/2 CERAMIC WIRE GUIDE
2	4	1004-200	#4 UNIBODY HOUSING
1	56	9004-201	3/8-16 x 1-1/2 HEX HEAD 12 PT SCREW
ITEM	QTY	PART #	DESCRIPTION



NOVO
PRECISION

TOLERANCE UNLESS OTHERWISE STATED		GAO	DRAWING / PART NO.
Δ 1/8	FRACT +/- 1/8	DWN KPL	1004-014
$\pm$ 0.0001	X 0.001	CHK	PART NAME
ϕ 0.0002	XX 0.010	SCALE	#4 PWS ASSY.
ϕ 0.0005	XXX 0.005	DATE 4/2/02	CUSTOMER
ϕ 0.0010	XXXX 0.0005		EXPLODED VIEW